

Fig. 1
Prior Art





Fig. 2
Prior Art



HAFT ASSEMBLY SAFETY MECHANIS

Andrew J. Whitton, et al.

Docket No. 091395-9214 (4596-TC-AU)

Sheet 2, of 6

Fig. 3




Fig. 4





Fig. 5



10005649-022600

FIG. 6





FIG. 7



209220 64958001

HAFT ASSEMBLY SAFETY MECHANIS

Andrew J. Whitton, et al.

Docket No. 091395-9214 (4596-TC-AU)

Sheet 4 of 6

Fig. 8





Fig. 9



Sheet 5 of 6

FIG. 12





FIG. 13



2022051958001 10085649-022602